

ATTY: ROBERT B. REESER, III; PHONE: (314) 621-5070




FIG. 1

ATTY: ROBERT B. REESER, III; PHONE: (314) 621-5070

2/6




FIG. 2

ATTY: ROBERT B. REESER, III; PHONE: (314) 621-5070




FIG. 3

4/6




FIG. 4

ATTY: ROBERT B. REESER, III; PHONE: (314) 621-5070




Fig. 5

METHODS AND APPARATUS FOR OPERATING GAS TURBINE ENGINES

INVENTOR: EPHRAIM J. GUTMARK, et al.

DOCKET: 139141

ATTY: ROBERT B. REESER, III; PHONE: (314) 621-5070

6/6




FIG. 6